

Oil Field Environmental Incident Summary

Incident: 20160323134805 **Date/Time of Notice:** 03/23/2016 13:48

Responsible Party: THUNDERBIRD RESOURCES LP

Well Operator: THUNDERBIRD RESOURCES LP

Well Name: LANGE 44-31-2H

Field Name: BENNETT CREEK

Well File #: 23634

Date Incident: 3/20/2016 **Time Incident:** 06:30

Facility ID Number:

County: MCKENZIE

Twp: 147

Rng: 99

Sec: 31

Qtr:

Location Description:

Submitted By: Allen Cobb

Received By:

Contact Person: Allen Cobb
9400 N. BROADWAY #600
OKLAHOMA CITY, OK 73114

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	70	Barrels	70	Barrels		
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk. Only saltwater.

Areal Extent:

Potential Environmental Impacts:

None the spill stayed on location and was cleaned up within 6 hours of the spill.

Action Taken or Planned:

Spill was vacuumed up in less than 6 hours after the spill. Most was contained in pump containment. We are adding additional safety devices to the system

Wastes Disposal Location: Saltwater was recovered and put back in the saltwater tank on location.

Agencies Involved:**Updates**

Date: 3/23/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was contained to the well pad. NDIC has oversight.